


Colour grader





DEVICE INTRODUCTION

1. Measuring sensor
2. White balance adjustment tool
3. Flour intake ring
4. Cover
5. White balance calibration button
6. Measuring button


This device is designed to measure the colour of the flour

1. Put the white balance adjustment tool (pos 2) onto the measuring sensor (pos 1)
2. Push the calibration button (pos 5) to calibrate the unit
3. Take away the adjustment tool (pos 2)
4. Put the flour intake ring (pos 3) onto the measuring sensor (pos 1)
5. Fill flour in the ring (pos 3) (about 1 cm high)
6. Put the cover (pos 4) onto the flour
7. Push the measuring button (pos 6)
8. Read the result on the right side of the display
9. Compare the result on the Kent Jones Colour chart



NEW COLOUR GRADER CONVERSION CHART TO KENT JONES COLOUR

NEW COLOUR GRADER RESULT NO:



KENT JONES COLOUR NO: